

Fig. 1



Microsoft Access - [hwworkinput1.mdb] File Edit View Insert Tools Window Help

Field Name	Data Type	Description
Order Number	AutoNumber	
Date Received	Date/Time	
Date Started	Date/Time	
Customer Name	Text	
Street Number	Text	
Street Name	Text	
Nearest Cross Street	Text	
Town	Text	
Town Section	Text	
Phone Number	Text	
Customer Account Number	Number	
Requested By	Text	
Service Number	Text	
Account Charged	Text	
Description of Job	Text	Extract Water Main Break and Customer Water Quality Work Orders
Markout Required Y or N	Text	
Job Priority	Text	
Date Completed	Date/Time	

Field Properties

General

Field Size: 45

Format: >

Input Mask:

Caption:

Default Value:

Validation Rule:

Validation Text:

Required: No


Allow Zero Length: No

Indexed: No

This property cannot be modified in linked tables.

Design view. F6 = Switch panes. F11 = Help

Fig. 2

FIG. 3



Microsoft Access - [tblHydrantFlushing] File Edit View Insert Tools Window Help

Field Name	Data Type	Description
ID	AutoNumber	
HYDRANT #	Text	
FLUSH DATE	Date/Time	
STATIC PRESSURE	Number	
FLOW-GPM	Number	
GALLONS FLOWED	Number	
CL2 RESIDUAL	Number	
RESIDUAL PRESSURE	Number	
REMARKS	Memo	
EMPLOYEE NUMBER	Text	
SIZE OPENING	Text	
FULL FLOW TEST	Text	
COMMENTS	Text	

Field Properties

General	Lookup
Field Size	150
Format	
Input Mask	
Caption	
Default Value	
Validation Rule	
Validation Text	
Required	No
Allow Zero Length	No
Indexed	No

Design view. F6=Switch panes. F11=Help

This property cannot be modified in linked tables.

Fig. 4



Microsoft Word 2000 - [File] [Edit] [Format] [Records] [Tools] [Window] [Help]

Select Order Number to find: 14056 [New] [Print] [Service] [Status] [History] [Back] [Save] [Exit]

Order Number:	14056	Customer Name:	
Sev Hyd Valve #:	4340	Street Number:	310
Service Order #:	41800780	Street Name:	FISHER AV
Date Received:	12/1/98	Cross Street:	WEST LAKE AV
Date Started:	12/15/98	Town:	NEPTUNE
Date Completed:	12/15/98	Town Section:	
Requested By:		Phone Number:	
Job Priority:	ROUTINE	Account Charged:	730174
Description of Job:	WATER MAIN BREAK	Miscout Requirement:	No

Notes: SERVICE SADDLE DETERIORATED. CEMENT MAIN COLLAPSED HAD TO REPLACE AND RETAP FOR SERVICE. CONT. DUG LEAK.

Employee Assigned To Job: EVANS F. Date Assigned: 12/15/98
 Ticket Number: 072 Total # Employees On Job: 2
 Total Time To Complete: 6 Time Arrived On Job: 12:30 PM

Record: 12/15/98 11:50 AM [Filter] [Print] [Next] [Previous] [First] [Last]

Form View [Microsoft Word Document] [Microsoft Access] [Microsoft Excel] [Microsoft PowerPoint] [Microsoft Visual Basic] [Microsoft Visual FoxPro] [Microsoft Visual Studio] [Microsoft Visual Studio .NET] [Microsoft Visual Studio .NET 2003] [Microsoft Visual Studio .NET 2005] [Microsoft Visual Studio .NET 2008] [Microsoft Visual Studio .NET 2010] [Microsoft Visual Studio .NET 2012] [Microsoft Visual Studio .NET 2013] [Microsoft Visual Studio .NET 2014] [Microsoft Visual Studio .NET 2015] [Microsoft Visual Studio .NET 2016] [Microsoft Visual Studio .NET 2017] [Microsoft Visual Studio .NET 2018] [Microsoft Visual Studio .NET 2019] [Microsoft Visual Studio .NET 2020] [Microsoft Visual Studio .NET 2021] [Microsoft Visual Studio .NET 2022] [Microsoft Visual Studio .NET 2023] [Microsoft Visual Studio .NET 2024] [Microsoft Visual Studio .NET 2025] [Microsoft Visual Studio .NET 2026] [Microsoft Visual Studio .NET 2027] [Microsoft Visual Studio .NET 2028] [Microsoft Visual Studio .NET 2029] [Microsoft Visual Studio .NET 2030]

Fig. 5

[illegible]

Fig. 6


Fig. 7

Fig. 7



Microsoft Word - Hydrant Data

Hydrant Data

GOING TO: []
FLOW: []
SIZE: []

NEW RECORD

HYDRANT # HNT-95

FLUSH DATE	4/7/98	EMPLOYEE	1805040	STATIC PRESSURE	78
FLOW/GPM	1050	GALLONS FLOWED	15750	RESIDUAL PRESSURE	
CHLORINE	1	SIZE OPENING	4 INCH		

REMARKS: NO OFFSET

Record ID: 2102
INSTALLED: 3/23/98
REMOVED: []
STATUS: ACTIVE

REMARKS:

Microsoft Access

Fig. 8



Microsoft Access - [tblTotalPoints - Tab1] | File Edit View Insert Tools Window Help

Field Name	Data Type	Description
Order Number	AutoNumber	
Town	Text	
Street Name	Text	
Description of Job	Text	Like Water Main Break, Water Quality Complaint
Size of Main	Number	
Number of Customers Affected	Number	
Total Time of Shut Down (Hrs)	Number	
Expr1	Number	Results of Expression from the query that calculates the total points based on entered criteria
Expr2	Number	Results of Expression from the query that calculates the total points based on entered criteria
Expr3	Number	Results of Expression from the query that calculates the total points based on entered criteria
Expr4	Number	Results of Expression from the query that calculates the total points based on entered criteria
Expr5	Number	Results of Expression from the query that calculates the total points based on entered criteria
Expr6	Number	Results of Expression from the query that calculates the total points based on entered criteria
Expr7	Number	Results of Expression from the query that calculates the total points based on entered criteria

Field Properties

General | Tooltips

Field Size: Long Integer

Format: Auto

Input Mask:

Caption:

Default Value:

Validation Rule:

Validation Text:

Required: No

Indexed: No

The field description is optional. It helps you describe the field and is also displayed in the status bar when you select this field on a form. Press F1 for help on descriptions.

Design view | F6 = Switch panes | F11 = Help

Fig. 10



q:\p\date_Crossab

Town	Street Name	Total	Hydric	Water Main Break	Water Quality / Dirty Water	Water Quality Pressure Problem
NEPTUNE	FISHER AV	25		25		
BRADLEY BEACH	NEWARK AV	21		21		
BRADLEY BEACH	PARK FINCH AVE	15		15		
NEPTUNE	STANLEY ST	15		15		
NEPTUNE	WEST BANGS AVE	15		15		
OCEAN TOWNSHIP	MONMOUTH RD	15		15		
ALLENTOWN	ALLENTOWN ST	14		14		
MIDDLETOWN	FLORENCE AV	13		13		
NEPTUNE CITY	GREEN AVE	13		13		
ASSBURY PARK	MATLISON AV	13		13		
ASSBURY PARK	SECONO AV	13		13		
ASSBURY PARK	ELM STREET	13		13		
UNION BEACH	BRANWICK AVE	12		12		
ASSBURY PARK	THIRD AV	11		11		
BRADLEY BEACH	OCEAN AV	11		11		
NEPTUNE	DUPRANO RD	11		11		
OCEAN GROVE	HECK AV	11		11		
LONG BRANCH	BRADLEY AVE	10		10		
MIDDLETOWN	OCEANVIEW AV	10		10		
MIDDLETOWN	SEVENTH AV	10		10		
NEPTUNE	COCKBURN AVE	10		10		
NEPTUNE	STRATFORD AVE	10		10		
OCEAN TOWNSHIP	SEWARD AVE	10		10		
ABERDEEN	ANDOVER LA	9		9		
ABERDEEN	ARDMORE LA	9		9		
ABERDEEN	CARROLLA	9		9		
ABERDEEN	IRINGHAM AVE	9		9		
ASSBURY PARK	FIRST AV	8		8		
LONG BRANCH	ALBERT PL	8		8		
MIDDLETOWN	CENTER AVE	8		8		
MIDDLETOWN	HAMILTON AVE	8		8		
MIDDLETOWN	MAPLEWOOD AV	8		8		
MIDDLETOWN	PROSPECT AV	8		8		
NEPTUNE	LAKEWOOD RD	8		8		
NEPTUNE	ROBBINS RD	8		8		
OCEAN GROVE	OCEAN AV	8		8		
OCEAN TOWNSHIP	LAKEVIEW AV	8		8		
OCEAN TOWNSHIP	LAMBERT JOHNSON DR	8		8		

Fig. 11